


2017-2018 Fire Safety Inspection Report Summary and Violation Correction Plan

District: West Irondequoit
Facility Address:
Inspector: Kelly Wasson
Inspection Date: 10/16/2017

Facility: Irondequoit High School
Facility Code Number: 0001
NYS Inspector Registry: 0309-7117
Escort(s): John Conti

Violation Code	Violation Description	Violation Observed	Corrective Action to be Taken (Completed by District)	Date to be Completed
2D-1	All emergency rescue windows are identified by signs as specified on the window and or on any window shades, blinds, or curtains, or above the window.	Room 2031 items were found on the rescue window. These items need to be removed.	Removed Decals from window	10-24-17
12E-1	No electrical system hazards were observed or reported.	Christmas lights were found in room 3026.	Removed lights	10-24-17
14C-2	Doors requiring closers are not rendered inoperable by removal of the closer or the installation of any nonautomatic hold open device.	Main office doors propped open.	Repaired door closer	10-24-17

I, Kelly Wasson, inspected this building and the information in this Fire Survey Inspection Summary represents, to the best of my knowledge and belief, an accurate description of the building and conditions I observed. I have maintained my certification requirements pursuant to Title 19 Part 1208B


Kelly Wasson 0309-7117

10/17/17
Date


2017-2018 Fire Safety Inspection Report Summary and Violation Correction Plan

District: West Irondequoit
Facility Address:
Inspector: Kelly Wasson
Inspection Date: 10/16/2017

Facility: Rogers Southlawn School
Facility Code Number: 0003
NYS Inspector Registry: 0309-7117
Escort(s): John Conti

Violation Code	Violation Description	Violation Observed	Corrective Action to be Taken (Completed by District)	Date to be Completed
15C-2	Artwork and teaching materials in hallways are limited to not more than 20% of the corridor wall area.	Rooms 166, 170 There was excessive art work in the hallway.	REMOVED EXCESSIVE ART WORK	10-25-17
15D-2	Curtains, drapes, hangings and other decorative materials suspended from walls or ceilings shall comply with Section 807.4 and shall not exceed 10 Percent of the specific wall or ceiling to which they are attached.	The vision panel on the door was covered. This is not allowed per SED	REMOVED ITEMS COVERING VISION PANEL	10-25-17

I, Kelly Wasson, inspected this building and the information in this Fire Survey Inspection Summary represents, to the best of my knowledge and belief, an accurate description of the building and conditions I observed. I have maintained my certification requirements pursuant to Title 19 Part 1208B


Kelly Wasson 0309-7117

10/17/17
Date


2017-2018 Fire Safety Inspection Report Summary
and Violation Correction Plan

District: West Irondequoit
Facility Address:
Inspector: Kelly Wasson
Inspection Date: 10/16/2017

Facility: Listwood School
Facility Code Number: 0027
NYS Inspector Registry: 0309-7117
Escort(s): John Conti

Violation Code	Violation Description	Violation Observed	Corrective Action to be Taken (Completed by District)	Date to be Completed
14C-2	Doors requiring closers are not rendered inoperable by removal of the closer or the installation of any nonautomatic hold open	Multiple doors found propped open	DOOR WEDGES HAVE BEEN REMOVED	10/25/17

I, Kelly Wasson, inspected this building and the information in this Fire Survey Inspection Summary represents, to the best of my knowledge and belief, an accurate description of the building and conditions I observed. I have maintained my certification requirements pursuant to Title 19 Part 1208B


Kelly Wasson 0309-7117

10/17/17
Date

**2017-2018 Fire Safety Inspection Report Summary
and Violation Correction Plan**

District: West Irondequoit
Facility Address:
Inspector: Kelly Wasson
Inspection Date: 10/16/2017

Facility: Concession Stand
Facility Code Number: 7030
NYS Inspector Registry: 0309-7117
Escort(s): John Conti

Violation Code	Violation Description	Violation Observed	Corrective Action to be Taken (Completed by District)	Date to be Completed
		There were no apparent issues at the time of the inspection.		

I, Kelly Wasson, inspected this building and the information in this Fire Survey Inspection Summary represents, to the best of my knowledge and belief, an accurate description of the building and conditions I observed. I have maintained my certification requirements pursuant to Title 19 Part 1208B



Kelly Wasson 0309-7117

10/17/17

Date


**2017-2018 Fire Safety Inspection Report Summary
and Violation Correction Plan**

District: West Irondequoit
Facility Address:
Inspector: Kelly Wasson
Inspection Date: 10/16/2017

Facility: Sproule Field House
Facility Code Number: 0021
NYS Inspector Registry: 0309-7117
Escort(s): John Conti

Violation Code	Violation Description	Violation Observed	Corrective Action to be Taken (Completed by District)	Date to be Completed
		There were no apparent issues at the time of the inspection.		

I, Kelly Wasson, inspected this building and the information in this Fire Survey Inspection Summary represents, to the best of my knowledge and belief, an accurate description of the building and conditions I observed. I have maintained my certification requirements pursuant to Title 19 Part 1208B



Kelly Wasson 0309-7117

10/17/17

Date


**2017-2018 Fire Safety Inspection Report Summary
and Violation Correction Plan**

District: West Irondequoit
Facility Address:
Inspector: Kelly Wasson
Inspection Date: 10/16/2017


Facility: Grandstand w/ Press box
Facility Code Number: 7019
NYS Inspector Registry: 0309-7117
Escort(s): John Conti

Violation Code	Violation Description	Violation Observed	Corrective Action to be Taken (Completed by District)	Date to be Completed
		There were no apparent issues at the time of the inspection.		

I, Kelly Wasson, inspected this building and the information in this Fire Survey Inspection Summary represents, to the best of my knowledge and belief, an accurate description of the building and conditions I observed. I have maintained my certification requirements pursuant to Title 19 Part 1208B



Kelly Wasson 0309-7117



Date


2017-2018 Fire Safety Inspection Report Summary
and Violation Correction Plan

District: West Irondequoit
Facility Address:
Inspector: Kelly Wasson
Inspection Date: 10/16/2017

Facility: Oakview School
Facility Code Number: 0009
NYS Inspector Registry: 0309-7117
Escort(s): John Conti

Violation Code	Violation Description	Violation Observed	Corrective Action to be Taken (Completed by District)	Date to be Completed
17H-2	Means of egress are provided with emergency illumination.	Room 24 exit light out.	REPLACED BULB -	10-28-17

I, Kelly Wasson, inspected this building and the information in this Fire Survey Inspection Summary represents, to the best of my knowledge and belief, an accurate description of the building and conditions I observed. I have maintained my certification requirements pursuant to Title 19 Part 1208B



Kelly Wasson 0309-7117

10/17/17
Date


2017-2018 Fire Safety Inspection Report Summary and Violation Correction Plan

District: West Irondequoit
Facility Address:
Inspector: Kelly Wasson
Inspection Date: 10/16/2017

Facility: Dake Junior High School
Facility Code Number: 0002
NYS Inspector Registry: 0309-7117
Escort(s): John Conti

Violation Code	Violation Description	Violation Observed	Corrective Action to be Taken (Completed by District)	Date to be Completed
14C-2	Doors requiring closers are not rendered inoperable by removal of the closer or the installation of any nonautomatic hold open device	Kitchen area, doors propped open. 350 Hallway doors propped open.	REMOVED DOOR WEDGES.	10/26/17
15D-2	Curtains, drapes, hangings and other decorative materials suspended from walls or ceilings shall comply with Section 807.4 and shall not exceed 10 Percent of the specific wall or ceiling to which they are attached.	Room 123, The vision panel was covered. This is not allowed by SED. Room 357 was equipped with light shades. This is not allowed by SED. Rooms 311, 184A doors were covered with artwork.	Room 123: REMOVE ITEMS COVERING VISION PANEL 357: REMOVED LIGHT SHADES 311 + 184A - REMOVED ARTWORK	10/26/17

I, Kelly Wasson, inspected this building and the information in this Fire Survey Inspection Summary represents, to the best of my knowledge and belief, an accurate description of the building and conditions I observed. I have maintained my certification requirements pursuant to Title 19 Part 1208B



Kelly Wasson 0309-7117

10/17/17

Date


2017-2018 Fire Safety Inspection Report Summary
and Violation Correction Plan

District: West Irondequoit
Facility Address:
Inspector: Kelly Wasson
Inspection Date: 10/16/2017

Facility: Iroquois School
Facility Code Number: 0004
NYS Inspector Registry: 0309-7117
Escort(s): John Conti

Violation Code	Violation Description	Violation Observed	Corrective Action to be Taken (Completed by District)	Date to be Completed
		There were no apparent issues at the time of the inspection.		

I, Kelly Wasson, inspected this building and the information in this Fire Survey Inspection Summary represents, to the best of my knowledge and belief, an accurate description of the building and conditions I observed. I have maintained my certification requirements pursuant to Title 19 Part 1208B



Kelly Wasson 0309-7117

10/17/17

Date


2017-2018 Fire Safety Inspection Report Summary
and Violation Correction Plan

District: West Irondequoit
Facility Address:
Inspector: Kelly Wasson
Inspection Date: 10/16/2017

Facility: Seneca School
Facility Code Number: 0006
NYS Inspector Registry: 0309-7117
Escort(s): John Conti

Violation Code	Violation Description	Violation Observed	Corrective Action to be Taken (Completed by District)	Date to be Completed
		There were no apparent issues at the time of the inspection.		

I, Kelly Wasson, inspected this building and the information in this Fire Survey Inspection Summary represents, to the best of my knowledge and belief, an accurate description of the building and conditions I observed. I have maintained my certification requirements pursuant to Title 19 Part 1208B



Kelly Wasson 0309-7117

10/17/17


Date

2017-2018 Fire Safety Inspection Report Summary
and Violation Correction Plan

District: West Irondequoit
Facility Address:
Inspector: Kelly Wasson
Inspection Date: 10/16/2017

Facility: Lakeview School
Facility Code Number: 0013
NYS Inspector Registry: 0309-7117
Escort(s): John Conti

Violation Code	Violation Description	Violation Observed	Corrective Action to be Taken (Completed by District)	Date to be Completed
		There were no apparent issues at the time of the inspection.		


Kelly Wasson 0309-7117

10/17/17
Date


**2017-2018 Fire Safety Inspection Report Summary
and Violation Correction Plan**

District: West Irondequoit
Facility Address:
Inspector: Kelly Wasson
Inspection Date: 10/16/2017

Facility: District Office
Facility Code Number: 1033
NYS Inspector Registry: 0309-7117
Escort(s): John Conti

Violation Code	Violation Description	Violation Observed	Corrective Action to be Taken (Completed by District)	Date to be Completed
		There were no apparent issues at the time of the inspection.		

I, Kelly Wasson, inspected this building and the information in this Fire Survey Inspection Summary represents, to the best of my knowledge and belief, an accurate description of the building and conditions I observed. I have maintained my certification requirements pursuant to Title 19 Part 1208B



Kelly Wasson 0309-7117

10/17/17

Date

**2017-2018 Fire Safety Inspection Report Summary
and Violation Correction Plan**

District: West Irondequoit
Facility Address:
Inspector: Kelly Wasson
Inspection Date: 10/16/2017

Facility: Helmer Nature Center Office
Facility Code Number: 0024
NYS Inspector Registry: 0309-7117
Escort(s): John Conti

Violation Code	Violation Description	Violation Observed	Corrective Action to be Taken (Completed by District)	Date to be Completed
		There were no apparent issues at the time of the inspection.		

I, Kelly Wasson, inspected this building and the information in this Fire Survey Inspection Summary represents, to the best of my knowledge and belief, an accurate description of the building and conditions I observed. I have maintained my certification requirements pursuant to Title 19 Part 1208B



Kelly Wasson 0309-7117

10/17/17

Date


**2017-2018 Fire Safety Inspection Report Summary
and Violation Correction Plan**

District: West Irondequoit
Facility Address:
Inspector: Kelly Wasson
Inspection Date: 10/16/2017

Facility: HNC Pavilion
Facility Code Number:
NYS Inspector Registry: 0309-7117
Escort(s): John Conti

Violation Code	Violation Description	Violation Observed	Corrective Action to be Taken (Completed by District)	Date to be Completed
		There were no apparent issues at the time of the inspection.		

I, Kelly Wasson, inspected this building and the information in this Fire Survey Inspection Summary represents, to the best of my knowledge and belief, an accurate description of the building and conditions I observed. I have maintained my certification requirements pursuant to Title 19 Part 1208B



Kelly Wasson 0309-7117

10/17/17

Date


**2017-2018 Fire Safety Inspection Report Summary
and Violation Correction Plan**

District: West Irondequoit
Facility Address:
Inspector: Kelly Wasson
Inspection Date: 10/16/2017

Facility: Colebrook School
Facility Code Number: 0032
NYS Inspector Registry: 0309-7117
Escort(s): John Conti

Violation Code	Violation Description	Violation Observed	Corrective Action to be Taken (Completed by District)	Date to be Completed
12E-1	No electrical system hazards were observed or reported.	Rooms 121, 129 Christmas lights were found in use.	Removed lights	10/23/17

I, Kelly Wasson, inspected this building and the information in this Fire Survey Inspection Summary represents, to the best of my knowledge and belief, an accurate description of the building and conditions I observed. I have maintained my certification requirements pursuant to Title 19 Part 1208B



Kelly Wasson 0309-7117

10/17/17

Date


2017-2018 Fire Safety Inspection Report Summary and Violation Correction Plan

District: West Irondequoit
Facility Address:
Inspector: Kelly Wasson
Inspection Date: 10/16/2017

Facility: Briarwood School
Facility Code Number: 0029
NYS Inspector Registry: 0309-7117
Escort(s): John Conti

Violation Code	Violation Description	Violation Observed	Corrective Action to be Taken (Completed by District)	Date to be Completed
15D-2	Curtains, drapes, hangings and other decorative materials suspended from walls or ceilings shall comply with Section 807.4 and shall not exceed 10 Percent of the specific wall or ceiling to which they are attached.	Room 146 Light filters were noted on the ceiling. Light filters are not allowed by SED. Room 146 and adjacent room had a valence on the windows. The valences must be flame retardant.	Light filters and valence have been removed.	10-25-17

I, Kelly Wasson, inspected this building and the information in this Fire Survey Inspection Summary represents, to the best of my knowledge and belief, an accurate description of the building and conditions I observed. I have maintained my certification requirements pursuant to Title 19 Part 1208B


Kelly Wasson 0309-7117


10/17/17
Date

2017-2018 Fire Safety Inspection Report Summary
and Violation Correction Plan

District: West Irondequoit
Facility Address:
Inspector: Kelly Wasson
Inspection Date: 10/16/2017

Facility: Brookview School
Facility Code Number: 0028
NYS Inspector Registry: 0309-7117
Escort(s): John Conti

Violation Code	Violation Description	Violation Observed	Corrective Action to be Taken (Completed by District)	Date to be Completed
		There were no apparent issues at the time of the inspection.		


Kelly Wasson 0309-7117


10/17/17
Date

2017-2018 Fire Safety Inspection Report Summary
and Violation Correction Plan

District: West Irondequoit
Facility Address:
Inspector: Kelly Wasson
Inspection Date: 10/16/2017

Facility: Department of Environmental Services
Facility Code Number: 3020
NYS Inspector Registry: 0309-7117
Escort(s): John Conti

Violation Code	Violation Description	Violation Observed	Corrective Action to be Taken (Completed by District)	Date to be Completed
		There were no apparent issues at the time of the inspection.		



Kelly Wasson 0309-7117

10/17/17

Date


**2017-2018 Fire Safety Inspection Report Summary
and Violation Correction Plan**

District: West Irondequoit
Facility Address:
Inspector: Kelly Wasson
Inspection Date: 10/16/2017

Facility: Environmental Services Barn
Facility Code Number: 3031
NYS Inspector Registry: 0309-7117
Escort(s): John Conti

Violation Code	Violation Description	Violation Observed	Corrective Action to be Taken (Completed by District)	Date to be Completed
		There were no apparent issues at the time of the inspection.		

I, Kelly Wasson, inspected this building and the information in this Fire Survey Inspection Summary represents, to the best of my knowledge and belief, an accurate description of the building and conditions I observed. I have maintained my certification requirements pursuant to Title 19 Part 1208B



Kelly Wasson 0309-7117

10/17/17

Date